

### 3. PHYSICAL DESTRUCTION REPORT

Due to the variety of conditions and interfaces that hard drives are donated to us, not all hard drives can be wiped by the same software or via the same process. This can be due to:

- 1.The hard drive's interface is incompatible with our hardware.
- 2.The hard drive failed the health test prior to being wiped.
- 3.The hard drive failed during the wiping process.

In these cases, we opt to physically destroy the entire hard drive. The hard drives listed below have been physically destroyed on-site via crushing so that the platters can not engage. Solid state drives are destroyed on-site via crushing so they are unable to be used. After crushing, all hard drives and solid state drives are sent to R2 Certified\* recycler for further physical destruction via shredding.

This document certifies that the customer proprietary information located on the hard drives listed below is unrecoverable due to the physical destruction of the drive.

Serial Number	Destruction Method	Technician
AKHN9NV58000	Shredded	John Smith
AKHN9NV57000	Shredded	John Smith
AKHN9NV57001	Shredded	Jane Doe
AKHN9NV57002	Shredded	Jane Doe